

U.S. Consumer Product Safety Commission

CPSC Stands for Safety

China Product Hazard Monthly Summary Bulletin

July 2022

中国 产品危害 每月小结 简报

2022 年七月

The China Product Hazard Monthly Summary Bulletin advises Chinese manufacturers of the most commonly occurring hazards posed by products they produce, such as batteries including lithium-ion batteries and other electrical/electronic products, violations of U.S. federal flammability standards for children's sleepwear, excessive lead levels in children's products, small parts choking hazards, and others. More information on specific cases listed below is available by clicking on the link or going to: CPSC's Recalls page.

《中国产品危害每月小结简报》的目的是提示中国厂商注意一些他们生产的产品最常出现的危害,诸如包括锂电池在内的电池以及其它电子和电器产品,违反美国联邦儿童睡衣阻燃标准,儿童产品含铅过量,因小部件而导致窒息等问题。简报中相关个案的详细情况,可以点击 CPSC's Recalls page,查看公告全文。

22-764	The ceramic pulleys used in the switchblade and drifter kiteboarding kites can cause the bridle line connection to break, which reduces performance in steering and control of the kite, causing the kiteboarder to lose control of the kite, posing an injury hazard. 用于弹簧刀和漂流风筝的瓷制滑轮 会使缰绳连接断裂,从而减弱风筝导航和控制的能力,致使漂流风筝者对风筝失去控制,构成受伤危害。
22-192	The fabric playhouses and play tents fail to meet an industry flammability
	standard for these products, posing a risk of burn injuries to children. 织物剧场和游戏帐篷 不符合对这些产品的行业阻燃标准,对儿童构成烧伤风险。
<u>22-186</u>	The weld attaching the hammock stand to the base can break, posing a fall
	hazard.
	连接吊床架和底座的焊接会断裂,构成跌倒危害。
22-758	The tent's stove jack ring can deteriorate when exposed to high temperatures
	from contact with a stove pipe and create smoke inside the tent, posing a risk of
	injury from smoke inhalation.
	帐篷的炉顶环因和炉管接触而暴露在高温下会锈蚀,从而在帐篷内产生烟雾,构成由
	于吸入烟而受伤的风险。

<u>22-185</u>	The multipurpose helmets do not comply with the positional stability and retention
	system requirements of the U.S. CPSC federal safety standard for bicycle helmets.
	The helmets can fail to protect in the event of a crash, posing a risk of head injury.
	多功能头盔不符合美国消费安全委员会的联邦自行车头盔位置稳定性和保持系统要求
	安全规定。头盔在遇到冲撞时不能起到保护作用,构成头部受伤风险。
<u>22-183</u>	There is a risk of battery fires with the electric unicycles . Consumers are urged to
	stop using the unicycles due to fire hazard.
	用于 电动独轮平衡车 的 电池 有着火风险消费者被告诫由于构成火灾危害,应停止使用
	独轮平衡车。
22-757	The utility terrain vehicles' cockpit rear panel between the seats and the cargo
	bed can overheat and melt the plastic, posing a fire hazard.
	多用途地形车 位于座椅和货箱之间的座舱后板可能会过热而熔化塑料部分,构成火灾
	危害。
<u>22-755</u>	The 9-drawer chests are unstable if they are not anchored to the wall, posing tip-
	over and entrapment hazards that can result in death or serious injuries to
	consumers.
	九屉衣橱 如果不固定在墙上的话会不稳,构成翻倒和羁绊危害,从而导致消费者死亡
	和严重受伤。
22-181	The pom poms on the touch book can detach, posing a choking hazard to young
	children.
	可触摸书上的绒球 会脱落,对幼儿构成气管堵塞危害。